




ACTIVELY ERODING BANKS

Percent of AHI survey units with some active bank erosion.
(Number of AHI units per catchment)



Universal Transverse Mercator Projection

Figure 6.3. Percent of AHI survey units with some active bank erosion, by catchment (from AHI data).

Earth Design Consultants, Inc.		Green Point Consulting	
	800 NW Starker, Suite 31	2625 NW Mulkey Avenue	
	Corvallis, OR 97330	Corvallis, OR 97330	
	(541) 757-7896	(541) 752-7671	
http://www.earthdesign.com		http://www.peak.org/~brophy/	